

M-8403
1 of 1




FIG. 1 (Prior Art)




FIG. 2 (Prior Art)




FIG. 3

M-8403
2 of 19






FIG. 4

M-8403
3 of 11



09540238-040400




FIG. 7

M-8403
4 of 11




FIG. 8A




FIG. 8B

FIG. 9A





FIG. 9B



5 M-8403
of 1

M-8403
6 of 9

FIG.9C






FIG.9D



095402268-DRAFT001


M-8403
7 of 11

FIG. 9E



09540238 - 040400

FIG. 9F



09540236 - Q4Q100

FIG- 9G





FIG. 10

M-8403
10 of 19

00000000000000000000000000000000



Pool Id	Any Firewall Faulty in Pool	Replacement Firewall	Firewall List
			55

50 ↗

FIG. II A

00000000000000000000000000000000


Firewall List

Port	MAC Address	IP Address	This Firewall Faulty	Next Firewall in Pool
			55	
Port	MAC Address	IP Address	This Firewall Faulty	Next Firewall in Pool
			⋮	⋮

FIG. II B

Mar 03
12 of 19

FIG. 12




M-8403
13 of 19

FIG. 13

09540238 - 040300




FIG. 14


M-8403
15 of 19

FIG. 15

M-8403
16 of 19





FIG 16.

M-8403
17 of 19





FIG. 17

18403
of 1700
18/5




M-8403
19 of 191800
L

FIG. 19